


Supplies: unfinished pine lumber for safety (not manufactured wood, plywood, particle board, etc.), wood glue, nails or screws.

Time: 1 hour to cut the wood, fit together snugly, glue, dry, and sand each box.







Plan View- Top Plan View- Bottom



Perspective- Open End



- Sides *or* Ends could be swapped for mirror orientation of plan



Perspective- Mirrored Orientation

